

10428949 May 2024

Ultimate Dana 60° Axle for Ford[®] Bronco[®]

Crate Axles

| Kit Component | Part # |
|--------------------|----------|
| ELD rear axle 5.38 | 10151195 |
| ELD rear axle 4.88 | 10151197 |
| ELD rear axle 4.56 | 10151198 |
| ELD rear axle 4.10 | 10151200 |
| ELD rear axle 3.73 | 10151202 |
| ARB rear axle 5.38 | 10151203 |
| ARB rear axle 4.88 | 10151227 |
| ARB rear axle 4.56 | 10151228 |

| Optional Components | Part # |
|--------------------------------|-------------------|
| U-joint strap kit (driveshaft) | 3-70-28X |
| Air compressor | (Customer Choice) |
| Locker Wiring Harness | 10021771 |

Axle Features

- "Bolt in, plug in" axles for Bronco
- 5.38, 4.88, 4.56, 4.10 & 3.73 axle ratios
- 35 spline chromoly axle shafts
- ELD or ARB locking differential
- Able to accept existing brake package or Aftermarket brake packages
- · 3.5" diameter .400" wall tubing
- Heavy duty cast iron differential cover
- Semi float rear axle design
- Dual row tapered roller wheel bearings
- Fluid filled with synthetic 75W140, 2.6 L
- Pinion yoke 1350 1/2 round strap style
- Axle internals are Dana 60 for strength and ease of service.
- Original Bronco track bar WILL NOT work. Dana track bar 10428919 included.
- Brake line and ABS line mounting locations included on axle tube brackets.

Installation Notes

- Original Bronco wheel speed/ABS sensors and mounting bolts must be removed from stock axles and reused.
- Uses original Bronco calipers, rotors & brake pads.
- Dana pigtail provided to connect UD60 ELD to OE vehicle locker wiring harness.
- Dana wire pigtail provided for a non-ELD Bronco. Switch/relay required for installation.
- Longer bolts may be required for some suspension points: use grade 10.9.
- Suspension torques from Bronco service manual should be followed.
- 1350 series driveshaft u-joint will be required at axle
- Stock Bronco wheel studs and bolt pattern maintained to reuse stock or AFM wheels. (M12 x 1.5 x 12 wheel studs, 6 x 5.5" bolt pattern)
- Most aftermarket suspension kits will work with Dana Bronco UD60 rear axle assembly
- Ensure brake lines and fittings do not make contact with other components.
- ARB axle assemblies must have adequate air compressor.
 - Between 85 and 105 psi.
 - Supply clean filtered air (no dust, dirt etc.)
- Route airlines away from moving/hot components.
- Allow for suspension travel when securing air lines to vehicle chassis.
- See Bronco service manual for general axle installation information.

Ultimate Dana 60° for Ford[®] Bronco[®]

Operational Notes

- Users should familiarize themselves with the new axle ratios & larger tire sizes, as pedal feel and driving feel may change.
- · Any gear ratio and tire size changes require reprogramming of vehicle computer.

Service Items

| Component | Part # | | | Smart # (For Ordering) | Dana #/BOM (Assembly ID #) |
|--|--------------------|---------------|--|------------------------|----------------------------|
| Axle Shaft Assy LH Rear | Dana 10151245 | | | SF-L60BR373E-69 | 10151202 |
| Axle Shaft Assy RH Rear | Dana 10151246 | | | SF-L60BR410E-69 | 10151200 |
| Input Yoke Straps | Dana 3-70-28X | | | SF-L60BR456E-69 | 10151198 |
| | | | | SF-L60BR538E-69 | 10151195 |
| Air Locking Differential | ARB RD166 | | | SF-L60BR456A-69 | 10151228 |
| ELD Differential | Dana 10024012 | | | SF-L60BR4SBA-69 | 10151227 |
| ELD Pigtail | Dana 10264409 | | | SF-L60BR538A-69 | 10151203 |
| Bearing Strap Assembly | 3-70-28X | | | SF-L60BR4SBE-69 | 10151197 |
| | | | | SF-L60BR538E-73 | 10301899 |
| Wheel Studs | FORD_ACPZ-1107-A | | | SF-L60BR538E-76 | 10262909 |
| Wheel Speed Sensor Rear | FORD_MB3Z-2C190-B | | | SF-L60BR513E-73 | 10416785 |
| Rear Pinion Seal | Dana 50637 | | | SF-L60BR488E-73 | 10409433 |
| Pinion Tail Bearing | Dana 550359/550358 | | | SF-L60BR456E-73 | 10409445 |
| Pinion Head Bearing | | | | SF-L60BR410E-73 | 10409451 |
| | Dana 550361/550360 | | | SF-L60BR373E-73 | 10409453 |
| Differential Bearing | Dana 550363/550362 | | | SF-L60BR538A-73 | 10409455 |
| | | | | SF-L60BR513A-73 | 10416789 |
| Rear Driveshaft Kits | | | | SF-L60BR488A-73 | 10409459 |
| | | Part # | | SF-L60BR456A-73 | 10409460 |
| SWB (2 Door) Part time (No 4A Option) Dana 103 | | Dana 10335062 | | SF-L60BR513E-76 | 10416774 |
| LWB (4 Door) Part time (No 4A Option) Dana 1033505 | | Dana 10335059 | | SF-L60BR4SBE-76 | 10409379 |
| SWB (2 Door) Part time (4A Option) | | Dana 10335066 | | SF-L60BR456E-76 | 10409385 |

Dana 10335064

If you need additional information, please contact your Dana Aftermarket representative. For assistance please contact the Spicer TechService Department at 800-621-8084. Thank you for your continued support of Dana Aftermarket products!

LWB (4 Door) Part time (4A Option)

| 01-L00D11070L-70 | 10-03-00 |
|------------------|----------|
| SF-L60BR538A-73 | 10409455 |
| SF-L60BR513A-73 | 10416789 |
| SF-L60BR488A-73 | 10409459 |
| SF-L60BR456A-73 | 10409460 |
| SF-L60BR513E-76 | 10416774 |
| SF-L60BR4SBE-76 | 10409379 |
| SF-L60BR456E-76 | 10409385 |
| SF-L60BR410E-76 | 10409387 |
| SF-L60BR373E-76 | 10409395 |
| SF-L60BR538A-76 | 10409403 |
| SF-L60BR513A-76 | 10416779 |
| SF-L60BR488A-76 | 10409405 |
| SF-L60BR456A-76 | 10409406 |
| | |

SF-L60BR513E-69

SF-L60BR513A-69

SpicerParts.com

Dana Aftermarket Group PO Box 1000 Maumee, Ohio 43537 Warehouse Distributors: 1.800.621.8084

Follow SpicerParts f 🗇 🖻 in



10151196

10151204